Date: Monday 9/23/19 Report prepared by: Name: David Kenney

Job Title: Clerk of the Works

My Work Hours Onsite: Start: 8 a.m. Stop: 9:30 a.m. Contractor Work Hours: Start: 7:30 a.m. Stop: 4:00 p.m.

Location of Work: Black Point Beach Jobsite

Site Visitors: None

Site Condition: Clear at first then mostly cloudy by 9:30, Temp around 70 degrees and climbing, Dry site

Work Force:

CONTRACTOR NAME	TRADE	# OF EMPLOYEES	EMPLOYEE NAME
Pinder Construction	Operator	1	?
	Working Supt	1	Rick Pinder
	Laborer	1	Ned

Contractors Equipment:

JOB SITE EQUIPMENT					
CONTRACTOR	ТҮРЕ	QUANTITY	OPERATIONAL		
Pinder Construction	287C CAT mini-loader, rubber tracks	1	Y		
	320 CAT Excavator, steel tracks	1	Y		
	304E CAT mini-loader	I	Y		

L110G Volvo Loader	1	N
6010 Mantis Crane	1	N
D5C CAT dozer, steel tracks	1	N

Work Performed:

DESCRIPTION OF WORK ACTIVITY				
ACTIVITY NO.	WORK PERFORMED			
	Relocating rocks, boulders, etc from the northeast end of the groin to facilitate sheet pile installation.			
	Installing wood blocking for securing existing sheet piling.			

DAILY INSPECTION REPORT BLACK POINT BEACH GROIN RESTORATION

3/3

Extra work: N/A	
Delays: N/A	
Testing: N/A	
Field Memos: N/A	

Discussions: I talked to Rick about having our first meeting this week. We agreed to shoot for this Friday, 7 a.m. on the jobsite if the weather is nice. I called Keith Neilson and asked if he could make it to the meeting at that time. Keith said yes he could. I will send out the agenda and meeting request to Rick, Keith, Charles (Design), and Steve (Black Point).

Comments: I received notice last Wednesday nite that I was confirmed as the Clerk of the Works for the Black Point Beach Club. The first time I was able to get by the jobsite was last Saturday and I noticed that the Contractor had already mobilized equipment and had begun a little work at the east end of the pier. I took some "pre-existing" photos today but they don't accurately depict the pre-existing conditions because the Contractor had already mobilized.

Job Photos: 18 photos including equipment photos, staging areas, access/egress routes, pre-existing conditions, and ongoing work.