DAILY INSPECTION REPORT BLACK POINT BEACH GROIN RESTORATION

1/3

Date: Tuesday 10/01/19
Report prepared by:December W. HonnayName: David Kenney
Job Title: Clerk of the Works
My Work Hours Onsite: Start: 10:30 a.m.Stop: 11:30 a.m.Contractor Work Hours: Start: 7:00Stop: 4:30 +/-Location of Work: Black Point Beach Jobsite
Site Visitors: NoneSite Condition: overcast, Temp 70 in morning then clear, temp 70's in afternoon

Work Force:

CONTRACTOR NAME	TRADE	# OF EMPLOYEES	EMPLOYEE NAME
Pinder Construction	Operator	1	Reg Pinder
	Working Supt	1	Rick Pinder
	Laborer	1	Ned
	Iron Worker	1	?

Contractors Equipment:

JOB SITE EQUIPMENT			
CONTRACTOR	ТҮРЕ	QUANTITY	OPERATIONAL
Pinder Construction	287C CAT mini-loader, rubber tracks	1	Y
	320 CAT Excavator, steel tracks	1	Y
	304E CAT mini-loader	1	Y

DAILY INSPECTION REPORT BLACK POINT BEACH GROIN RESTORATION

2/3

L110G Volvo Loader 6010 Mantis Crane	l I	Y N
D5C CAT dozer, steel tracks	1	N

Work Performed:

DESCRIPTION OF WORK ACTIVITY		
ACTIVITY NO.	WORK PERFORMED	
	Contractor chipping away at a rock blocking the installation of sheet #33.	
	There were rocks blocking the installation of sheet #32 yesterday and it took	
	them most of the day to clear that and ultimately drive sheet #32. See photos	
	for the pieces of rock chipped away. They will install sheet piles once this	
	obstruction is cleared.	
	Ned and ? were setting up for installation of tie rods beginning at the east end	
	of the groin while Rick and Reg battled the rock in the way.	

DAILY INSPECTION REPORT BLACK POINT BEACH GROIN RESTORATION

Extra work: N/A

Delays: N/A

Testing: N/A

Field Memos: N/A

Discussions: Rick told me they worked until about 6:30 p.m. last night getting in sheet #32.

Comments: This rock blocking sheet #33 should be the last obstruction. There are only 5 more sheets to install and they have probed for these last 5 sheets and found no obstructions (other than for sheet #33).

Job Photos: 4 photos including trying to chip the rock away from sheet #33, armor stone placed on the south side, and 2 of the rock pieces chipped away for installation of sheet #32.