

Black Point's Master Plan

- The Master Plan reflects the community's value and enables BPA to define its own strategy for maintaining & sustaining the high quality of life offered by the community
- The Master Planning process inventories community assets, identifies short and long term needs for improvements and key areas for protection
- The Master Plan's goals and strategies creates a "road map" of actionable items and a timeline for implementation
- Planning is a continuous process, and BPBCA's first Master Plan will provide a foundation for future decision making & plan refinement





Land Use & Zoning

Rentals and Property Maintenance

- Zoning rules require a minimum one-week rental period. Short-term rentals are not permitted.
 - Is there an administrative process for this?
 - Any enforcement issues?
- Recent adoption of accessory apartment zoning language, in response to new state statutes.
 - ADUs cannot be used as rentals.
- There are property maintenance guidelines. Blight may be perceived as an issue by some. Town has a blight ordinance.
 - Boat and boat trailer storage Issues?
 - If a blight ordinance is considered, enforcement mechanism needs to be discussed.






Land Use & Zoning

Parking and Driveways

- On-street parking not permitted due to narrow roadways.
- Off-street parking only required for properties with accessory apartments, which need a minimum of 3 spaces.
- Is there a desire to include off-street parking requirements for new construction?
 - Tradeoff between impervious surfaces and stormwater runoff and need for adequate vehicle storage.
 - Recommend pervious materials for driveways such as gravel and permeable pavement/pavers





Land Use & Zoning

Potential Considerations

- Consider creating stormwater management standards for new construction, incorporating best-management practices for on-site stormwater management and treatment.
- Consider modifying zoning regulations to require at least two full feet of freeboard for structures in coastal hazard areas and consider exempting freeboard from minimum height calculations.
- Consider strengthening sight line requirements for intersections (hedges, fences, etc).
 - Increase clearance distance from 10 ft
 - Create additional sight line buffer requirements around stop signs.
- Off street parking requirements?



Stop sign obstructed by bushes on Whitecap Road at East Shore Dr. (Source: Google Street view circa 2013)







Costal Storm Flood Risk

Greatest inundation risk at beaches.

Seawall infrastructure generally protects properties from Category 1 inundation.

Category 2 storms and stronger pose threat to properties, with those along East Shore Drive at greatest risk.

Worst Case Huricane Inundation (USACE 2008)

Category 1

Category 2


Category 3

Category 4









#	Access Point	Amenities
1	Blue Heron Ct	Water access, benches
2	Osprey Rd	Beach access, Osprey pier access, boat float, boat storage, kayak rack, bench, bike rack, swim float
3	Brightwater Rd	Water access, benches
4	Saltaire Ave	Water access, benches
5	Sea Spray Ave	Kayak launch, kayak racks, bench
6	Sea Crest Ave	Water access, benches
7	Sea View Ave	Boat ramp, boat storage, shared beach access (boat priority)

#	Access Point	Amenities
8	Sea Breeze Ave	Beach access, parking, bike rack south pier access, swim float
9	Whitecap Rd	Beach access, golf cart parking, bike rack steel pier access
10	Indianola Rd	Beach access, swim beach, bike rack, steel pier access
11	Nehantic Dr	Beach access, car/golf cart parking, benches, bike rack, north pier access
12	Bellaire Rd	Water access
13	Billow Rd	Water access


Issues: Beaches

- Seaweed and eelgrass on beaches. Potential strategies:
 - Beach raking/grooming note that beach raking using motorized equipment requires a DEEP General Permit for Coastal Maintenance. Additional permits may be required depending on nature of activity.
 - Implement strategies to minimize eelgrass bed disturbance needs to be a collaborative approach beyond BPBCA borders.
- Maintenance (prevent painting/graffiti on seawalls, etc.)
- Need for additional park benches next to right-of-way that are accessible to elderly
- Beach erosion and nourishment
 - Continue to pull sand up from the waterline during the winter and pull back down in the spring to minimize erosion.
 - Maintain groin/pier infrastructure in a state of good repair.



Issues: Eelgrass

- Seaweed/eelgrass
 management frequently cited
 as an issue smell and
 associated insects
- According to CTDEEP data, the entire Niantic Bay frontage of BPBCA is an eelgrass bed.
- Strategies to reduce eelgrass disturbance include:
 - Avoid anchoring in eelgrass beds.
 - Buoy mooring lines
 - Limiting use of propellors within eelgrass bed zones.
 - Limiting boat speeds/wakes



Issues: Boating

- Boat beach maintenance (rocks, seaweed removal)
- Need for rack system for paddleboards
 - Need to identify priority location(s).
- Kayak racks currently free and first come first served some residents drop their kayaks and never use them.
 - Create a registration system?
 - Establish user fee?
 - Upland storage area?
 - How would these be managed or "honor system"
- Kayak accessibility vs. compatibility with bathers at Sea View Beach
- Community notification during storms



Kayak racks on the Pattagansett Estuary on Old Black Point Rd.



Issues: Docks & Piers

- Feedback received regarding need for permanent dock made with durable materials and providing additional capacity
 - Current floating docks are unsafe to stand on, particularly for elderly.
 - Dock space is limited and can only accommodate one boat at a time, creating log jams
- Daily maintenance and cleaning of piers
- Need for clear signage

Follow up items:

- Gather feedback on perceptions of docking facilities, and willingness to pay for improvements
- Is there room for either of the boat floats to be enlarged?




Issues: Docks & Piers

- Steel Pier repaired in 2019
 - New sheet piles on north side, pressure grouting fill, and new concrete topping slab
- Remaining piers/groins were assessed in 2020 (GNCB report). Needed improvements identified include:
 - Ongoing maintenance sealing, patching, and repair of concrete and epoxy surfaces
 - Repairs and enhancements to armor stone
 - Drainage pipe repairs
 - Raising each pier 1 foot.
 - These items were anticipated to cost \$1.84 million (in 2020 dollars) over a 30-year period.
 - Discussion of changes to charter to allow annual collection of funds for major capital projects as opposed to one-time special assessments?









Harbor Management Plan

- Plan amended in 2019
- Recommendations for Black Point Planning Unit include:
 - Moorings should be used primarily for shorefront property owners.
 - Limit impacts to intertidal flats, beaches, and other coastal resources
 - Continue water access and activities in accordance with association regulations
- Recommendations for Pattagansett Planning Unit include:
 - Maintain restricted speed area
 - Priority area for shellfish restoration
 - Prevent conflicts between coastal infrastructure and shellfish habitat areas





Coastal Resilience

East Lyme Coastal Resilience, Climate Adaptation, and Sustainability Study (CRASS) completed in 2018.

Key Issues impacting BPBCA:

- Sea level rise (SLR) State of CT has adopted a 20-inch sea level rise by 2050 as a standard for coastal resilience planning.
- Coastal flooding from extreme weather events. CT likely to experience more frequent and stronger storms, and impacts amplified by SLR.
- Structures in flood zones many in BPBCA, especially on east side of East Shore Road.
- Pump station infrastructure in flood zones.

Recommendations impacting BPBCA:

- Include freeboard in local zoning, in alignment with state SLR standards.
- Address drainage issues at Black Point Road at Burnap Road – prevent inundation through installation of backflow preventer on stormwater culvert under railroad.
- Perform critical roadway alterations for emergency access and climate adaptation.
- Evaluate and address critical infrastructure in coastal flood zones (such as East Shore Pump Station).



Hazard Mitigation

Natural Hazard Mitigation Plan for East Lyme updated in 2017

Key issues are similar to those identified in the 2018 CRASS study

Recommendations impacting BPBCA:


- Develop a checklist for land development applicants that cross-references the specific regulations and codes related to disaster resilience (BPBCA could partner with Town of East Lyme on this task).
- Pursue elevation of properties that suffer flood damage, prioritizing repetitive loss properties in the Niantic Bay area.
- Apply freeboard standards of one foot or more when requiring elevations for renovations or new construction in coastal flood zones.
- Relocate the wastewater pumping station in the Black Point area so that it is outside of the flood risk area or pursue other flood mitigation alternatives.
- Investigate funding sources and the feasibility of elevating locally owned roads with an emphasis
 on those needed for evacuation



East Lyme POCD

East Lyme Plan of Conservation and Development (POCD) last updated in 2020. Recommendations that are relevant to BPBCA include:

- Incorporating stormwater management best practices into zoning regulations.
- Address flooding issues on Black Point Road at Burnap Road.
- Implement recommendations from Hazard Mitigation Plan and CRASS report.





Recreation & Programs

Facilities

- Clubhouse tennis/pickleball courts (2)
- Nehantic tennis courts (2)
- Youth sized basketball court
- Shuffleboard (2)
- Bocce
- Gaga ball pit
- Playscape & playground
- Multi-purpose playfield

Programs

- Men's & Women's Club
- Tennis lessons
- Kids Summer Recreation Program
- Bocci and Pickleball Leagues
- Annual 5k road race
- Community events (bonfires, parade, BBQs)
- Yoga classes
- Swim lessons

Follow up items:

- Survey questions to determine interest and demand for additional programs/investments in facilities
- Willingness to pay



Clubhouse

- Used for official BPBCA meetings, annual meetings, and recreational programs such as Women's Club and Men's club.
- Recent improvements include new roof, renovated bathrooms, and new floors.
- Typically, not used in the winter

Follow up items:


- Survey questions to determine demand for year-round usage and programs
- Willingness to pay for other upgrades (weatherization, IT, AV, kitchen upgrades)





Transportation

- All roads in Black Point are classified as Local roadways by CTDOT. Old Black Point Road north of Woodland is considered a Collector Road.
 - Primary access to BPBCA via West End Road/Attawan Rd and Old Black Point Road
- Shared use roadways within BPBCA boundaries accommodate cars, golf carts, cyclists, and pedestrians.
 - Narrow road widths
 - Sight line/visibility issues at some intersections, particularly on East Shore Drive
- Conflicts with vehicles/trailers using the Sea View Avenue boat launch





Next Steps....

- Generate community awareness of master planning process through information on website, update at Board of Governor's Meeting & Social Media
- Disseminate Community "Initial Findings" Slide Deck through BPBCA's website
- Refine Draft online community survey for input and revisions. Target Survey Launch in next two weeks, if possible.

